

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No 128105

RECEIVED FROM

Approved For Release 2001/03/04 : CIA-RDP81B00879R000500080112-9

DATE REC'D 1-16-57		P.O. NO. 9075		VENDOR PACKING SLIP NO. 10520	
CONTRACT CODE NO. 322	DRAWING NUMBER 000000	DWG. DASH OR STANDARD PART NO. 10188	DWG. REV. 0	LOT NO. 0	CLASS NUMBER 00
CHARGE TO 10	QUANTITY RECEIVED 10	DRAWING NO. AND DESCRIPTION		QUANTITY	REMARKS
		780163-50 PLUG REPT MEL CANNON		10	
		1/17/57 AM 3103-24-20 F			
				ACCEPTED	REJECTED
RECEIVED BY		INSPECTED BY		DATE 1/17/57	
		Dua		REJECTS RETURNED ON SHIP MEMO NO.	

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No 128142

2861 E. COLORADO ST., PASADENA 8, CALIF.

RECEIVED FROM

DATE REC'D 1-17-57

P.O. NO. 9077

VENDOR PACKING SLIP NO. 34934

CONTRACT CODE NO. 322	DRAWING NUMBER 000000	DWG. DASH OR STANDARD PART NO. 3022	DWG. REV. 0	LOT NO. 0	CLASS NUMBER 00	OPER. NUMBER 00	BUY CLT. CODE NO. 02
CHARGE TO 11	QUANTITY RECEIVED 11	DRAWING NO. AND DESCRIPTION		QUANTITY	REMARKS		
		780163-50 BOLT CAD PLATE STEEL		11			
		AMCN AM 6-244					
				ACCEPTED	REJECTED		
RECEIVED BY		INSPECTED BY		DATE 1/18/57			
		Dua		REJECTS RETURNED ON SHIP MEMO NO.			

Approved For Release 2001/03/04 : CIA-RDP81B00879R000500080112-9